



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Supervisor DRH

Minerals Regulatory Program

May 22, 2007:

Mine Name: Levan Chicken Creek
Operator Name: Sunroc Corp

Permit number: M230016
Inspection Date: 06/13/2007
Time: 1:45-2:45P

Inspector(s): Tom Munson
Other Participants: none
Mine Status: active

Weather: Sunny

Elements of Inspection

	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

To see the level of activity at the site.

Inspection Summary:

There was no activity on the levan West site, but there was active mining occurring at the levan East site. An area adjacent to the site was disturbed, but after talking with the operator it was determine that this disturbance was a repair of some spring flooding in the area. I informed Kelly, the onsite manager of my concerns, and he assured me it was associated with Levan Land and Livestock company.

Conclusions and Recommendations:

The large mine permit be finished and permitted as quickly as possible.

Inspector's Signature Thomas Munson

Date: 6/14/07

Directions to Site:

The site is located in the South Fork of Chicken Creek.

Page 2 of 2

Inspection Date: 06/13/07; Report Date:06/14/07

Mine Number:M230016

Inspector's tm:pb

cc: Operator


US Forest Service, Tom Shore, Sanpete Ranger District,540 North Main, Ephraim, Ut 84627

Photos

O:\M023-Juab\M0230016-Levan-chickencreek\iinspections\insp-06132007.doc



LEVAN EAST INACTIVE



2007.06.13 13:56



2007.06.13 13:55


4 FLOODING REPAIR

X




2007.06.13 13:57

ENTRANCE TO MINE OF COINTRY ROAD



2007.06.13 13:47



2007.06.13 13:55


HELVIA BART



2007.06.13 13:47




2007.06.13 13:47



2007.06.13 13:44

AREA FIXED FOR FLOOD & DAMAGE



2007.06.13 13:47

LEAVE EAST



2007.06.13 13:44



2007.06.13 13:44